

PPE Donning

1 Perform hand hygiene.

.....

2 Put on gown. Tie at neck and then waist.



3 Put on mask. Pull over Chin.



4 Put on eye protection



5 Put on gloves, ensuring they go over the cuffs of the gown.

